



652 Oliver Street
 Williamsport, PA. 17701 U.S.A.

Tel. 570-323-6181
 Fax. 570-327-7101
 www.lycoming.com

SERVICE INSTRUCTION

DATE: August 25, 2010

Service Instruction No. 1526
 Engineering Aspects are
 FAA (DER) Approved

SUBJECT: Piston Usage

MODELS AFFECTED: All Lycoming reciprocating aircraft engines

TIME OF COMPLIANCE: As required for replacement

This Service Instruction is being issued to inform owners and operators of the following new piston part numbers. These new pistons have been manufactured to be equivalent to the current piston part numbers. These new pistons are singly interchangeable with the corresponding current piston part number as listed below in the Table.

| CURRENT PISTON P/N | NEW PISTON P/N |
|--------------------|----------------|
| LW-10545-S | 14D23907 |
| LW-10207-S | 14D23908 |
| LW-11487-S | 14D23909 |
| LW-14610-S | 14D23910 |



| ISSUED | | | REVISED | | | PAGE NO. | REVISION |
|--------|-----|------|---------|-----|------|----------|----------|
| MO | DAY | YEAR | MO | DAY | YEAR | | |
| 08 | 25 | 10 | -- | -- | -- | 1 of 1 | -- |