



652 Oliver Street  
Williamsport, PA. 17701 U.S.A.

Tel. 570-323-6181  
Fax. 570-327-7101  
www.lycoming.com

# SERVICE INSTRUCTION

DATE: January 18, 2012

Service Instruction No. 1526C  
(Supersedes Service Instruction No. 1526B)

SUBJECT: New Piston Part Numbers

MODELS AFFECTED: All Lycoming reciprocating aircraft engines

TIME OF COMPLIANCE: As required for replacement

### NOTE

Incomplete review of all the information in this document can cause errors. Read the entire Service Instruction to make sure you have a complete understanding of the requirements

This Service Instruction identifies additional new piston part numbers that superseded existing piston part numbers in Table 1. All of the new pistons have been manufactured to be equivalent to the superseded piston part numbers shown in Table 1. The new pistons are interchangeable and can be mixed in the same engine in any location with superseding pistons in Table 1.

TABLE 1 CURRENT AND NEW PISTON PART NUMBERS	
*SUPERSEDED PISTON P/N	NEW SUPERSEDING PISTON P/N
LW-10545-S	14D23907
LW-10207-S	14D23908
LW-11487-S	14D23909
LW-14610-S	14D23910
75089	14D23912
LW-12733	14D23913
LW-15357	14D23914
75413	14D23915
LW-18725	14B23917
LW-18729	14B23918
* Superseded piston P/N will be used until stock is depleted.	



ISSUED			REVISED			PAGE NO.	REVISION
MO	DAY	YEAR	MO	DAY	YEAR	1 of 1	C
08	25	10	01	18	12		